

# AZ-post

## Configuration Guide

NCDData Services

Manufacturing Software Solutions

P.O. Box 3954  
Show Low, AZ 85901

[www.NCDDataServices.com](http://www.NCDDataServices.com)

[NCDData@frontiernet.net](mailto:NCDData@frontiernet.net)

(928) 532-8045


**Revised 27-OCT-2005**

<b>Introduction</b> .....	<b>5</b>
The Challenge .....	5
The Goal.....	6
The AZpost Concept.....	7
Prior to manufacturing process .....	8
During manufacturing process.....	8
Ready for machining.....	9
<b>The Environment</b> .....	<b>10</b>
Installation.....	10
File & Folder Structure .....	10
The APTsource CLFile.....	11
The Machine Code.....	13
<b>The Configuration File</b> .....	<b>15</b>
General Concepts .....	15
SECTION ONE – Default Limits and Modes .....	15
Predefined postprocessor statements .....	16
CLEARP/ value .....	16
FEDRAT/ MAXUPM, upm.....	16
LIMITS/XAXIS, xmin,xmax, YAXIS, ymin,ymax, ZAXIS, zmin,zmax .....	16
MCHTOL/ AAXIS, value.....	16
SELECT/ TOOL, AUTO .....	16
SEQNO/ start-value, INCR, increment-value.....	16
SPINDL/ MAXRPM, rpm .....	16
SET/ AAXIS, PLUS, CLW .....	17
SET/ AAXIS, TYPE, 1 .....	17
SET/ CIRCLE, QUADRT, OFFSET, INCR .....	17
SET/ CIRCLE, QUADRT, RADIUS.....	17
SET/ CLIPZ, value.....	17
SET/ COMMSG, start_characters, end_characters .....	17
SET/ CYCLE, DEPTH, ABS .....	17
SET/ DATIME, ON .....	18
SET/ FOOTER, ON .....	18
SET/ FORMAT, BLANKS, ON.....	18
SET/ FORMAT, PLUS, ON .....	18
SET/ FORMAT, ZEROS, ON .....	18
SET/ LOADPT, x-value, y-value, z-value, a-value .....	18
SET/ NCDEXT, string .....	18
SET/ ORIGIN, value.....	19
SET/ PPRINT, LIST, ON .....	19
SET/ TLCOMP, ON .....	19
OFF .....	19
SET/ TOOL, MAX, value.....	19
SET/ TOOL, LIST, ON .....	19
SET/ UNITS, INCHES, OUT, INCHES .....	19
SECTION TWO – Register Definitions and Values .....	20
G Register features:.....	22

M Register features: .....	22
SECTION THREE – Program MACRO Sequences .....	23
Postprocessor Key Words .....	24
SEQN    Numeric value of sequence number for next (current) block .....	24
CURTL    Numeric value of the current tool .....	24
NEXTL    Numeric value of the next tool.....	24
GAGEZ    Numeric value of the tool gauge length (set length).....	24
PIVOTZ    Numeric value of the tool gauge point to tool pivot point or.....	24
distance from machine table to A-axis center-line. ....	24
CLEARP    Numeric value of Z-axis at clearance from part zero .....	24
HOMEX    Numeric value of X-axis at its home position (FROM) .....	24
HOMEY    Numeric value of Y-axis at its home position (FROM) .....	24
HOMEZ    Numeric value of Z-axis at its home position (FROM).....	24
FEED    Numeric value of current feed rate (upm or upr).....	24
RPM    Numeric value of current spindle speed in RPM.....	24
FIXTUR    Numeric value of current fixture code.....	24
COOLNT    Numeric value of current coolant code.....	24
PROGID    Text value (numeric) of program ID (from PARTNO) .....	24
PARTNO    Text value of program description (from PARTNO) .....	24
TPRINT    Text value of current tool description (from TPRINT) .....	24
If used followed by a > character it will be applied.....	24
to the next block as a machine code comment.....	24
Predefined Macros .....	25
<b>MACRO/ START</b> .....	25
<b>MACRO/ FROM</b> .....	26
<b>MACRO/ FROM4</b> .....	26
<b>MACRO/ TLCHG1</b> .....	28
<b>MACRO/ TLCHG</b> .....	29
<b>MACRO/ GOHOME</b> .....	30
<b>MACRO/ RESTAR</b> .....	31
<b>MACRO/ RESTAR4</b> .....	31
Same as MACRO/RESTAR but is called by the AZpost postprocessor when the program is a MULTAX tool path and has (6) parameter GOTO records.	
<b>MACRO/ PRGEND</b> .....	31
<b>MACRO/ PRGEND</b> .....	32
<b>MACRO/ PRGEND4</b> .....	32
Appendix A.....	33
Sample Configuration File.....	33


# Introduction

## The Challenge




The challenge in postprocessing has always been to make the part program (APT source) as independent of the machine tool as possible. Making the part program independent of the machine tool allows the APT source file to be post-processed for different machine tools (of the same type) with little change to the program. This allows flexibility and efficiency on the shop floor when the part is ready for manufacture since re-routing to a different machine tool would be expedited.

## The Goal



Remove unique machine tool syntax from the part program (APT source) and put this information in a configuration file whose name can be referenced in the part program. The specific machine tool can then be re-targeted by simply referencing a different configuration file.

# The AZpost Concept



## Prior to manufacturing process

- Develop a **postprocessor executable** for each customer machining group.
- Create a custom **configuration** file for each specific machine tool.
- Create a **CATIA ptable** that targets each specific machine tool configuration using the **MACHIN/** statement (see ptable start macro below).

```
/
*START_NC_INSTRUCTION                NC_START_MACRO
*START_SEQUENCE
MACHIN/VMC4X, HAASVF, UNITS, INCHES, OUT, INCHES, OFF
PARTNO %MFG_IDENTIFIER %MFG_MACHINE_NAME
*END
*END
/
```

## During manufacturing process

- Create a CATIA manufacturing process (**CATProcess**) referencing the specific CATIA ptable. (Selected from postprocessor words table pull-down in Part Operation).
- Create **APTsource** file using CATIA “Generate NC output in batch” tool.

The APTsource file produced by CATIA will be **targeted** to the correct machine tool configuration and machining group based on the information from the CATIA ptable. The part program (APTsource) may now be postprocessed for scheduled machining in the shop or can be held (targeted) in APTsource form until scheduled for machining (see aptsource MACHIN/ below).

```
MACHIN/VMC4X, HAASVF, UNITS, INCHES, OUT, INCHES, OFF
PARTNO 123456 PART OPERATION POSTPROCESSOR TEST
$$ OPERATION NAME : Tool Change.2
$$ Start generation of : Tool Change.2
TLAXIS/ 0.000000, 0.000000, 1.000000
FROM / 0.00000, 0.00000, 6.00000
$$ TOOLCHANGEBEGINNING
CUTTER/ 1.000000, 0.000000, 0.500000, 0.000000, 45.000000,$
0.000000, 1.500000
TPRINT/T2 - SPOT DRILL 90 DEG
LOAD/TOOL,1,LENGTH, 4.528000
COOLNT/ON
```

## **Ready for machining**

The APTsource can be postprocessed if scheduled for the original targeted machine tool.

< OR >

If scheduled for a different machine tool, the part program can be re-targeted by simply changing the APTsource MACHIN/ reference to the correct machine tool configuration file and then postprocessing.

# The Environment

## *Installation*

1. Create directory (folders) structure if initial installation (see file & folder structure).
  - a. Create \Azpost folder.
  - b. Create \Azpost\bin folder.
  - c. Create \Azpost\cfg folder.
2. Detach **pp\_name.zip** file and unzip into a temporary folder.
3. Move **pp\_name.exe** files to \azpost\bin folder.
4. Move **mt\_name.cfg** files to \azpost\cfg folder.
5. Move **mt\_name.pptable** files to the CATIA pptables folder.

Note: Typical CATIA pptables folder

C:\Program Files\Dassault Systemes\B13\intel\_a\startup\Manufacturing\PPTables

## *File & Folder Structure*

### **\AZpost**

<b>\bin</b>	Contains postprocessor executable files (.exe.)
<b>\cfg</b>	Contains machine tool configuration files (.cfg)

When not using the **Manufacturing Work Bench** a Desk top shortcut can be created for each postprocessor executable in the Azpost \bin folder. Each machine tool should have a configuration file in the Azpost /cfg folder. Each configuration file must have a file extension of .cfg and the file name must not exceed six (6) characters not counting the .cfg extension.

To postprocess an aptsource cfile the aptsource file can be dragged and dropped on the postprocessor desk top icon. Postprocessor output files will be created in the same folder as the aptsource cfile. Typical output files are created as follows:

<b>Prg_name.NCD</b>	Machine control readable part program.
<b>Prg_name.NCL</b>	Expanded cross reference listing of machine code and aptsource including and diagnostic information.
<b>Prg_name.NCS</b>	Status file containing diagnostic information and Additional tabulated program information

# The APTsource CLFile

## SAMPLE.APTSource CATIA output

Configuration File

PPRINTs before 1<sup>st</sup>  
Cutter statement

```
PPRINT MACHIN FROM 8.5" X 4.5" X .5" ALUMINUM STOCK
PPRINT LOC PART ZERO AT:
PPRINT X = 0 IN FROM LEFT EDGE OF STOCK .5"
PPRINT Y = 0 IN FROM FRONT EDGE OF STOCK .5"
PPRINT Z = 0 AT BOTTOM OF STOCK
```

```
MACHIN/VMC4X,HAASVF,UNITS,INCHES,OUT,INCHES,OFF
PARTNO 1234 PART OPERATION POSTPROCESSOR TEST FANUC GENERIC 3-AXIS
```

```
TLAXIS/ 0.000000, 0.000000, 1.000000
FROM / 0.00000, 0.00000, 6.00000
```

```
CUTTER/ 0.375000, 0.375000, 0.000000, 0.005000, 0.000000,$
0.000000, 2.000000
```

```
TPRINT/ T1 - 3/8 DIA TWIST DRILL LENGTH 4.0
LOAD/TOOL,1,LENGTH, 4.000000
COOLNT/ON
```

Tool Change  
information

```
$$ OPERATION NAME : DRILL 4 HOLES
SPINDL/RPM, 1200.0000,CLW
```

```
RAPID
GOTO / 0.50000, 0.50000, 4.50000
RAPID
GOTO / 0.50000, 0.50000, 0.70000
CYCLE/DRILL,DEPTH, 0.500000,CLEAR, 0.200000,IPM, 12.000000
GOTO / 0.50000, 0.50000, 0.50000
GOTO / 0.50000, 3.50000, 0.50000
GOTO / 7.50000, 3.50000, 0.50000
GOTO / 7.50000, 0.50000, 0.50000
CYCLE/OFF
RAPID
GOTO / 7.50000, 0.50000, 4.50000
```

CYCLE statement

```
CUTTER/ 0.500000, 0.005000, 0.245000, 0.005000, 0.000000,$
0.000000, 2.000000
```

```
TPRINT/ T3 - 1/2 DIA END MILL LENGTH 2.500
LOAD/TOOL,3,LENGTH, 2.500000
COOLNT/ON
```

```
$$ OPERATION NAME : PROFILE CONTOUR OUTSIDE
PPRINT PROFILE CONTOUR OUTSIDE
SPINDL/RPM, 1050.0000,CLW
RAPID
GOTO / 1.00000, -1.00000, 0.50000
FEDRAT/IPM, 30.0000
GOTO / 1.00000, -1.00000, 0.00000
```

```

CUTCOM/LEFT
GOTO / 1.00000, -0.75000, 0.00000
INTOL / 0.00394
OUTTOL/ 0.00000
AUTOPS
INDIRV/ 0.00000, 1.00000, 0.00000
TLON,GOFWD/ (CIRCLE/ 0.50000, -0.75000, 0.00000,$
0.50000),ON,(LINE/ 0.50000, -0.75000, 0.00000,$
0.50000, -0.25000, 0.00000)

FEDRAT/IPM, 5.0000
INDIRV/ -1.00000, 0.00000, 0.00000
TLON,GOFWD/ (CIRCLE/ 0.50000, 0.50000, 0.00000,$
0.75000),ON,(LINE/ 0.50000, 0.50000, 0.00000,$
-0.25000, 0.50000, 0.00000)

GOTO / -0.25000, 3.50000, 0.00000
CUTCOM/OFF
GOTO / -0.30000, 3.55000, 0.00000
GOTO / -0.30000, 3.55000, 0.50000

COOLNT/OFF
SPINDL/OFF
END
FINI


```



Program end

## The Machine Code

### SAMPLE.NCD Machine Code output from postprocessor



FOOTER, ON

(TOTAL MACHINING TIME = 36716.70)  
(PROGRAM SIZE IN BYTES = 604)

⌘

# The Configuration File

## *General Concepts*

The configuration file is a plain text file. Most editors can be used to edit the file. The Windows “Word Pad” editor is recommended. The file extension for the configuration file must be .cfg and this extension can be registered with Windows for editing by the Word Pad editor. If other document editors (i.e. Word) are used, fonts and formatting must not be used (ie. turned off) and the file must be saved with extension .CFG.

## **SECTION ONE – Default Limits and Modes**

Section one contains APT predefined postprocessor statements that define default limits and programming modes. The syntax for the statements follow standard APT rules as shown in the following example:

```
LIMITS/ XAXIS,-40,40, YAXIS,-20,20, ZAXIS,-30,30 $$ AXIS LIMITS
```

LIMITS/	Major key word defining function (Axis limits) followed by a slash “/”
XAXIS	Minor key word defining feature (X-axis limits) followed by a comma “,”
-40,40	Numeric values (with or without decimal point “.”) separated by commas.
\$\$	Text following double dollar is ignored by the postprocessor and is used for commenting statement.

Comments \$\$ can be used anywhere and all text following the \$\$ in the statement is ignored by the postprocessor. A comma separator is not used after the last minor word or value in the statement.

Specific syntax is defined by the postprocessor and is documented in the postprocessor. The following syntax is basic to all postprocessors:

Note: Major & minor key words must be as shown in upper case. Lower case text must be replaced by appropriate numeric values.

## **Predefined postprocessor statements**

### **CLEARP/ value**

Sets a clearance plane for Z-axis motion based on program coordinates. This value can then be used in the MACROs defined in Section three of the configuration file.

### **FEDRAT/ MAXUPM, upm**

Sets the maximum feed rate in (units per minute) that can be programmed for the machine tool. Any programmed feed rate exceeding this value will create a warning in the listing and status files and the programmed value will be replaced or recomputed using the maximum upm value. See SET/ UNITS for defining units.

### **LIMITS/XAXIS, xmin,xmax, YAXIS, ymin,ymax, ZAXIS, zmin,zmax**

Sets the default axis values for postprocessor limit checking. Minor key word for specific axis followed by a minimum and maximum value couplet. This statement also sets the total travel as the difference between the maximum and minimum values for each axis.

### **MCHTOL/ AAXIS, value**

Sets a machine tolerance value when computing A-axis rotation based on tool axis vectors in the aptsource GOTO records. This allows tool axis vectors that are within the tolerance value of the YZ plane to be accepted without errors.

### **SELECT/ TOOL, AUTO**

Sets the selection (ready position) of the next tool for automatic output. See Section two in reference to register T1 for next tool. See Section three for use of T1 in MACROs.

### **SEQNO/ start-value, INCR, increment-value OFF**

Sets the sequence numbering in the machine code program (i.e. N). Sequence begins with the start value and is incremented using the increment value. Both values should be integer values (non decimal). The sequence numbering can also be turned off using the OFF minor word.

### **SPINDL/ MAXRPM, rpm**

Sets the maximum spindle RPM that can be programmed for the machine tool. Any programmed spindle speed exceeding this value will create a warning in the listing and status files and the programmed value will be replaced or recomputed using the maximum rpm value.

**SET/ AAXIS, PLUS, CLW  
CCLW**

Sets A-axis plus (+) rotation to either CLW or CCLW when looking in the plus X-axis direction. Default ISO standard PLUS = CLW.

**SET/ AAXIS, TYPE, 1  
2**

Type 1 (default) defines rotary angle signed plus or minus from rotary zero.  
Type 2 defines rotary angle absolute (unsigned) with sign determining direction of rotation.

**SET/ CIRCLE, QUADRT, OFFSET, INCR  
FULL ABS**

Sets the circular interpolation format in the machine code as follows:  
QUADRT breaks circles at quadrant points into multiple circle records.  
FULL outputs full 360 degree circles in one record.  
OFFSET specifies the arc center offset (IJK values) to output as either INCR for incremental or ABS for absolute from part program zero.

**SET/ CIRCLE, QUADRT, RADIUS  
FULL**

Sets the circular interpolation format in the machine code as follows:  
QUADRT breaks circles at quadrant points into multiple circle records.  
FULL outputs full 360 degree circles in one record.  
RADIUS specifies the output of radius (R) instead of arc center offsets.

**SET/ CLIPZ, value**

Sets a clipping value for the Z-axis. This value is used by the postprocessor to ignore any aptsources GOTO statement that exceeds this Z-axis value. Used to remove automatic CATIA created GOTO statements before and or after a CATIA tool change.

**SET/ COMMSG, start\_characters, end\_characters**

Sets the machine code comment message start characters and end characters.  
Default SET/COMMSG, (,)

**SET/ CYCLE, DEPTH, ABS  
INCR**

Sets the depth (Z,R) values used in the aptsources CYCLE statement to be either computed in absolute (ABS) from program zero or incremental (INCR) from the cycle reference plane.

**SET/ DATIME, ON**  
**OFF**

Sets the date and time stamp DATIME when the aptsource was postprocessed to be output in the beginning of the machine code program (as comments). This is can be turned ON or OFF using the corresponding minor key word.

**SET/ FOOTER, ON**  
**OFF**

Sets the machining time and program size to be output at the end of the machine code program (as comments). This is can be turned ON or OFF using the corresponding minor key word.

**SET/ FORMAT, BLANKS, ON**  
**OFF**

Sets the machine code format to insert blank spaces before each word address. This function can be turned ON or OFF using the corresponding minor key word.

**SET/ FORMAT, PLUS, ON**  
**OFF**

Sets the machine code format to insert a plus sign + when dimensional values are positive. This function can be turned ON or OFF using the corresponding minor key word.

**SET/ FORMAT, ZEROS, ON**  
**OFF**

Sets the machine code format to add a zero after the decimal point on decimal format when values are whole numbers. This function can be turned ON or OFF using the corresponding minor key word.

**SET/ LOADPT, x-value, y-value, z-value, a-value**

Sets the machine axis positions at program start in program coordinates. These values are used in computing time for program start, end, and tool changes. This command sets the HOMEX, HOMEY, and HOMEZ variables. These values are overridden by the aptsource FROM statement .

**SET/ NCDEXT, string**

Sets the file extension characters for the machine code file (default NCD).  
Example SET/ NCDEXT, MTF

**SET/ ORIGIN, value**

Sets the default zero offset (origin) value in the fixture offset register (i.e. G54).

**SET/ PPRINT, LIST, ON  
OFF**

Sets the aptsource PPRINTs before the first cutter statement to be output as comments. This is can be turned ON or OFF using the corresponding minor key word.

**SET/ TLCOMP, ON  
OFF**

Sets the postprocessor tool length compensation ON or OFF.  
Default SET/TLCOMP,OFF

**SET/ TOOL, MAX, value**

Sets the maximum value for the tool that can be programmed in the aptsource using the LOAD/TOOL or LOADTL command. Any programmed TOOL exceeding this value will create a error message in the listing and status files and the postprocessor will output a manual tool change in the machine code file.

**SET/ TOOL, LIST, ON  
OFF**

Sets the TOOL LIST to be output in the beginning of the machine code program (as comments). This is can be turned ON or OFF using the correponding minor key word.

**SET/ UNITS, INCHES, OUT, INCHES  
MM MM**

Sets the program UNITS of the input aptsource and the machine code OUTput units. If the UNITS and OUT are different the postprocessor will convert the input UNITS to the OUT put units for all dimensional data. The UNITS minor key word is followed by its minor key word INCHES or MM. The OUT minor key word is followed by its minor key word INCHES or MM.

## SECTION TWO – Register Definitions and Values

Section two contains register definitions similar to machine tool control CNC register groups. The syntax for these statements is shown and is described in the following examples:

	Parameters	
	1--2----3-----4--5-- 6 thru 48	Comment
REGDEF/	G1, G, 260, 260, T, 0,1,2,3,4,33,34	\$\$ INTERPOLATION

REGDEF/ Required for all register definitions (must be upper case followed by a '/')

1<sup>st</sup> Parameter Predefined register name (not definable by user).

2<sup>nd</sup> Parameter Word address user defined per machine tool code. Can be up to six characters

3<sup>rd</sup> Parameter Inch format specified in 3 digits as follows:

1 <sup>st</sup> Digit	Number of digits left of decimal point
2 <sup>nd</sup> Digit	Format as follows: 1 = Decimal point format output 2 = Leading zeros format output 4 = Trailing zeros format output 6 = Leading and trailing zeros format output
3 <sup>rd</sup> Digit	Number of digits right of decimal point

4<sup>th</sup> Parameter Metric format specified as 3 digits (same format as inch).

5<sup>th</sup> Parameter Modality of register (T or F) for true or false.

6 thru 48 All parameters following the modality parameter allow users to define numeric values for fixed features of the register. See values for fixed register features.

\$\$ Text following double dollar is used to comment function of the predefined postprocessor register.

All parameters are separated by a comma. A comma separator is not used after the last value in the statement.

Registers are predefined in the postprocessor (2<sup>nd</sup> parameter) and can not be added to or deleted from the configuration file. Word addresses, formats, modality, and numeric values of the predefined register can be changed.

The order that the registers are output in the machine code block is determined by the order that the registers are defined in section two of the configuration file. REGDEF records can be moved using the cut and paste method found in most text editors. Section two must end with an EOT (End of Table) statement.

#### Example 1:

```
REGDEF/ G1, G, 260, 260, T, 0,1,2,3,4,33,34 $$ INTERPOLATION
```

- G1 Predefined register for machine motion interpolation.
- G Word address machine code for motion interpolation.
- 260 Inch format for machine data. Two (2) digits to left of decimal. Zero (0) digits to right of decimal. Format 6 – No decimal point, leading and trailing zeros output.
- 260 Metric format same as inch
- T Modality true. If value same as current then don't output.
- 0 Value for rapid motion
- 1 Value for linear motion
- 2 Value for circular motion CLW
- 3 Value for circular motion CCLW
- 4 Value for machine dwell
- 32 Value for single thread cutting motion
- 33 Value for multiple thread cutting motion

#### Example 2:

```
REGDEF/ XX, X, 214, 413, T, $$ LINEAR ABSCISSA AXIS
```

- XX Predefined register for machine X-axis (Abscissa)
- X Word address machine code for machine X-axis
- 214 Inch format for machine data. Two (2) digits to left of decimal point. Four (4) digits to right of decimal point. Format (1) = decimal point output.
- 413 Metric format for machine data. Three (3) digits to left of decimal point. Three (3) digits to right of decimal point. Format (1) = decimal point output.
- T Modality true. If value same as current then don't output.

Note: No fixed features values are defined for dimensional registers

## **G Register features:**

G0	General	Undefined
G1	Interpolation	RAPID, LINEAR, CIRCULAR CLW, CIRCULAR CCLW, DWELL, SINGLE THREAD, THREAD CYCLE
G2	Plane Select	XYPLAN, ZXPLAN, YZPLAN
G3	Mode Select	ABSOLUTE, INCREMENTAL
G4	Spindle mode	SUM, RPM
G5	Feed rate mode	INVERSE_TIME, UPM, UPR
G6	Units mode	INCHES, MM
G7	Cutter rad comp	OFF, LEFT, RIGHT
G8	Tool length comp	ADD, SUBTRACT, CANCEL
G9	Cycle type	OFF, PECK, TAP_LEFT,
G10	Fixture offset	LOCAL, MACHINE, 1, 2, 3, 4, 5, 6, DATUM

## **M Register features:**

M0	General	Undefined
M1	Tool Change	LOAD/TOOL
M2	Coolant type	OFF, ON/FLOOD, MIST, THRU, TAP, AIR, AUX
M3	Spindle mode	OFF, CLW, CCLW, LOCK, CLAMP, UNCLAMP, LOW, HIGH
M4	Subroutine mode	MAIN_END, RETRACT, CLEAR
M5	Program control	STOP, OPSTOP, END, REWIND

## **SECTION THREE – Program MACRO Sequences**

Section three contains Macro definitions that contain machine code sequences constructed using the predefined registers and their values enclosed in parentheses. Macros are defined starting with the Major word MACRO followed by a slash followed by the predefined macro name. The body of the macro contains records containing the predefined registers and their values enclosed in parentheses. The end of the macro is identified with the major word END. An EOF record must be the last record in section three after the last macro. The syntax for these records is shown and is described in the following examples:

Example:

```
$$**** RETRACT MACRO SEQUENCE (Tool Change) ****
MACRO/RETRCT
M2 (9) $                $$ Coolant Off
G0 (28) G3 (91) YY (5.25) ZZ (CLEARP) $    $$ Machine Zero Y & Z-axis
END
```

The \$\$ can be used for documentation in the macro as shown and is ignored by the postprocessor. The macro starts with the major word MACRO followed by a "/" and the predefined name of the macro. Each predefined macro will be discussed below. The macro must end with the major word END. The body of the macro can contain up to six (6) records that represent the machine blocks to be output. Each record must end with a single \$ representing the end of block character. Each record can contain registers followed by a pair of parentheses () or text enclosed in a pair of double quotes "". Parentheses and quotes can not be mixed in a record. Key words representing postprocessor values can also be used inside the register parentheses as follows:

- ( ) - Empty parentheses specifies that the current value of the register for the specific macro will be output.
- (9) – A numeric value specifies that the register is to be output with the given numeric value according to the REGDEF format in section two. The value can be specified with or without a decimal point.
- (CLEARP) – A single key word that represents a postprocessor numeric value can be specified.

Each register and parentheses pair must be separated from the next by a space character. The end of block (\$ character) is not separated by a space and can be then followed by a comment beginning with a \$\$.

Key words are predefined by the postprocessor and the number of them can vary based on the specific postprocessor and postprocessor type. The specific key words are defined in the postprocessor documentation, but the basic key words are defined as follows:

### **Postprocessor Key Words**

SEQN	Numeric value of sequence number for next (current) block
CURTL	Numeric value of the current tool
NEXTL	Numeric value of the next tool
GAGEZ	Numeric value of the tool gauge length (set length)
PIVOTZ	Numeric value of the tool gauge point to tool pivot point or distance from machine table to A-axis center-line.
CLEARP	Numeric value of Z-axis at clearance from part zero
HOMEX	Numeric value of X-axis at its home position (FROM)
HOMEY	Numeric value of Y-axis at its home position (FROM)
HOMEZ	Numeric value of Z-axis at its home position (FROM)
FEED	Numeric value of current feed rate (upm or upr)
RPM	Numeric value of current spindle speed in RPM
FIXTUR	Numeric value of current fixture code
COOLNT	Numeric value of current coolant code
PROGID	Text value (numeric) of program ID (from PARTNO)
PARTNO	Text value of program description (from PARTNO)
TPRINT	Text value of current tool description (from TPRINT) If used followed by a > character it will be applied to the next block as a machine code comment.

The use of double quotes allows text to be specified for output in a block. This text is not formatted or checked in any way for correctness. This can be used for outputting special characters including blank records as follows:

```
" "      $$ OUTPUTS A BLANK MACHINE BLOCK
"%      $$ OUTPUTS THE REWIND STOP CHARACTER %
```

## **Predefined Macros**

### **MACRO/ START**

This macro is output at the immediate beginning of the machine code program. It can be used to output any special characters and any program identification information using the PROGID and PARTNO key words.

### **Example:**

#### [Aptsource:](#)

```
PARTNO 1234 PART OPERATION POSTPROCESSOR TEST FANUC GENERIC 3-AXIS
```

#### [Macro Specification:](#)

```
MACRO/START
"%
O (PROGID) PARTNO
END
```

#### [Machine Code Output:](#)

```
%
O1234 (PART OPERATION POSTPROCESSOR TEST FANUC GENERIC 3-AXIS)
```

## MACRO/ FROM

This macro is output at the beginning of the machine code program by the aptsource FROM statement. This macro can be used to output any initial registers and values. The FROM statement sets the HOMEX, HOMEY and HOMEZ values.

### Example:

#### Aptsource:

```
FROM / 0.00000, 0.00000, 6.00000
```

#### Macro Specification:

```
MACRO/ FROM  
G6 ( ) $ $$ INITIALIZE UNITS  
G1 (0) G2 (17) G3 (90) G7 (40) G8 (49) G9 (80) $ $$ INITIALIZE G CODES  
END
```

#### Machine Code Output:

```
N1 G20  
N2 G00 G17 G90 G40 G49 G80
```

## MACRO/ FROM4

Same as MACRO/ FROM but is called by the AZpost postprocessor when the program is a MULTAX tool path and has a (6) parameter FROM record.

## MACRO/ RETRACT

This macro is output before all tool changes except the first. This macro can be used to cancel any modes, turn of any functions and output any positioning moves prior to the tool change. The aptsources LOAD/ TOOL statement activates this macro.

### Example:

#### Aptsource:

```
LOAD/TOOL,1,LENGTH, 4.000000
```

#### Macro Specification:

```
MACRO/RETRACT
M3(5)$          $$ SPINDLE OFF
G3(91) G8(28) ZZ(0.) M2(9)$  $$ Z-AXIS TO MACHINE ZERO, COOLNT OFF
G8(49)$        $$ CANCEL TOOL LENGTH
M5(1)$         $$ MACHINE OPTIONAL STOP
END
```

#### Machine Code Output:

```
N13 M05
N14 G91 G28 Z0. M09
N15 G49
N16 M01
```

## **MACRO/ TLCHG1**

This macro is output for the first tool change. This macro is used to output any codes for the tool change block including tool description text. The aptsources LOAD/ TOOL statement activates this macro.

### **Example:**

#### Aptsource:

```
TPRINT/ T1 - 3/8 DIA TWIST DRILL LENGTH 4.0  
LOAD/TOOL,1,LENGTH, 4.000000
```

#### Macro Specification:

```
MACRO/TLCHG1  
TPRINT>                $$ Add TPRINT text to next block as comment  
TT () M1 (6) $         $$ Select and load the requested tool  
END
```

#### Machine Code Output:

```
N17 T3 M06 ( T3 - 1/2 DIA END MILL LENGTH 2.500)
```

## MACRO/ TLCHG

This macro is output for all tool changes except the first. This macro is used to output any codes for the tool change block including tool description text. The aptsource LOAD/ TOOL statement activates this macro.

### Example:

#### Aptsource:

```
TPRINT/ T3 - 1/2 DIA END MILL LENGTH 2.500  
LOAD/TOOL,3,LENGTH, 2.500000
```

#### Macro Specification:

```
MACRO/TLCHG  
TPRINT>                $$ Add TPRINT text to next block as comment  
TT () M1 (6) $         $$ Select and load the requested tool  
END
```

#### Machine Code Output:

```
N3 T1 M06 ( T1 - 3/8 DIA TWIST DRILL LENGTH 4.000)
```

## MACRO/ GOHOME

This macro is output to position the machine tool axes to the machine home position. This macro can be used to cancel any modes, turn off any functions and output the positioning moves. The aptsources GOHOME statement activates this macro.

### Example:

#### [Aptsource:](#)

```
GOHOME
```

#### Macro Specification:

```
MACRO/GOHOME
M3 (5) $                $$ SPINDLE OFF
G3 (91) G8 (28) ZZ (0.) M2 (9) $  $$ Z-AXIS TO MACHINE ZERO, COOLNT OFF
G3 (91) G8 (28) XX (0.) YY (0.) $  $$ X & Y AXIS TO MACHINE ZERO
G8 (49) $              $$ CANCEL TOOL LENGTH
M5 (0) $              $$ MACHINE STOP
END
```

#### Machine Code Output:

```
N13 M05
N14 G91 G28 Z0. M09
N14 G91 G28 X0. Y0.
N15 G49
N16 M00
```

## MACRO/ RESTAR

This macro is output after all tool changes. This macro can be used to restart any modes, turn on any functions and output any positioning moves after the tool change. The first aptsources GOTO statement activates this macro. All values defined in aptsources FEDRAT, SPINDL and ORIGIN statements after LOAD/TOOL are held until this GOTO statement.

### Example:

#### Aptsources:

```
CUTTER/ 0.500000, 0.005000, 0.245000, 0.005000, 0.000000,$
        0.000000, 2.000000
TPRINT/ T3 - 1/2 DIA END MILL LENGTH 2.500
LOAD/TOOL,3,LENGTH, 2.500000
COOLNT/ON
SPINDL/RPM, 1050.0000,CLW
RAPID
GOTO / 1.00000, -1.00000, 0.50000
```

#### Macro Specification:

```
MACRO/RESTAR
"G05P10000"
G1(0) G3(90) G10() XX() YY() SS() M3()$ $$ High speed machining mode
G8(43) ZZ() HH() M2()$ $$ First XY move after tlchg
END $$ First Z-axis
```

#### Machine Code Output:

```
N18 G05P10000
N19 G00 G90 G54 X1. Y-1. S1050 M03
N20 G43 H3 Z.5 M08
```

## MACRO/ RESTAR4

Same as MACRO/RESTAR but is called by the AZpost postprocessor when the program is a MULTAX tool path and has (6) parameter GOTO records.

## MACRO/ PRGEND

This macro is output to end the program, position the machine tool axes to the machine home position. This macro can be used to cancel any modes, turn off any functions and output the positioning moves. The aptsource END statement activates this macro.

### Example:

#### Aptsource:

```
END
```

#### Macro Specification:

```
MACRO/PRGEND
M2 (9) $          $$ COOLNT OFF
M3 (5) $          $$ SPINDLE OFF
G1 (0) G3 (91) G8 (28) ZZ (0.) $  $$ Z AXIS TO MACHINE ZERO
"G05P0"          $$ CANCEL High Speed Machining
G8 (49) $        $$ CANCEL TOOL LENGTH
G1 (0) G3 (91) G8 (28) XX (0.) YY (0.) $  $$ X & Y AXIS TO MACHINE ZERO
M5 ( ) $        $$ END PROGRAM
END
```

#### Machine Code Output:

```
N28 M09
N29 M05
N30 G91 G28 Z0.
N31 G05P0
N32 G49
N33 G91 G28 X0. Y0.
N34 M99
```

## MACRO/ PRGEND4

Same as MACRO/PRGEND but is called by the AZpost postprocessor when the program is a MULTAX tool path and has (6) parameter GOTO records.

## Appendix A

### Sample Configuration File

```
$$*****
$$ HAASVF.CFG - Haas VF 4-Axis Vertical Machining Center / Haas CNC
$$ (C) Copyright NCDATA Services 2004, 2005 www.NCDATAservices.com
$$ LAST CHANGED 17-JAN-2005 (sample)
$$*****
$$ SECTION ONE - Default Limits and Modes
$$*****
LIMITS/XAXIS,-40,40,YAXIS,-20,20,ZAXIS,-30,30 $$ AXIS TRAVEL LIMITS
SPINDL/MAXRPM, 20000 $$ MAXIMUM SPINDLE RPM
FEDRAT/MAXUPM, 200 $$ MAXIMUM UNITS FEED RATE
SEQNO/1,INCR,1 $$ SEQUENCE NUMBER
CLEARP/10.0 $$ CLEARANCE PLANE
MCHTOL/AAXIS,.010 $$ ROTARY AXIS TOLERANCE
$$SELECT/TOOL,AUTO $$ AUTOMATIC PRE-SELECT NEXT TOOL
$$SET/NCDEXT,MTF $$ MACHINE CODE FILE EXTENSION 'MTF'
SET/COMMSG,(,) $$ COMMENT MESSAGE START,STOP
SET/TOOL,MAX,18 $$ MAXIMUM TOOL NUMBER
$$SET/TLCOMP,ON $$ TURN ON TOOL LENGTH COMPENSATION
SET/FORMAT,BLANKS,ON $$ OUTPUT BLANKS BEFORE WORD ADDRESS
SET/FORMAT,PLUS,ON $$ TURN ON PLUS SIGN OUTPUT
SET/ORIGIN,54 $$ DEFAULT FIXTURE OFFSET
SET/UNITS,INCHES,OUT,INCHES $$ SET UNITS INPUT & OUTPUT TO INCHES
SET/LOADPT,0,20,30,0 $$ SET MACHINE STARTUP POSITION
SET/CLIPZ,98 $$ IGNORE CATIA RAPID GOTO IF Z>98
SET/CIRCLE,FULL,OFFSET,INCR $$ SET CIRCLES FULL,OFFSETS INCREMENTAL
SET/CYCLE,DEPTH,ABS $$ SET CYCLE DEPTHS ABSOLUTE
SET/TOOL,LIST,ON $$ TOOL LISTING IN HEADER
SET/PPRINT,LIST,ON $$ DISPLAY PPRINTS BEFORE 1ST CUTTER
SET/DATIME,ON $$ DISPLAYS DATE AND TIME STAMP
SET/FOOTER,ON $$ DISPLAYS TOTAL MACHINING TIME FOOTER
$$*****
$$ SECTION TWO - Register Definitions, Formats, Sequence and values
$$*****
$$ WORD FORMAT
$$ REGISTER, ADDR, INCH, METRIC, MODAL, VALUES
$$-----
-
REGDEF/ NN, N, 540, 540, F $$ SEQUENCE NUMBER
REGDEF/ G0, G, 260, 260, F, 98,99 $$ GENERAL PRE-FUNCTION
(RETRCT,NO_RETRCT)
REGDEF/ G1, G, 260, 260, T, 0,1,2,3,4,33,34 $$ INTERPOLATION MODE SELECT
(RAPID,LINEAR,CLW,CCLW,DWELL,THREAD)
REGDEF/ G2, G, 260, 260, T, 17,18,19 $$ INTERPOLATION PLANE SELECT
(XYPLAN,ZXPLAN,YZPLAN)
REGDEF/ G3, G, 260, 260, T, 90,91 $$ POSITIONING MODE SELECT
(ABSOLUTE,INCEMENTAL)
REGDEF/ G4, G, 260, 260, T, 96,97 $$ SPINDLE MODE SELECT (SUM,RPM)
REGDEF/ G5, G, 260, 260, T, 93,94,95 $$ FEED RATE MODE SELECT
(1/T,UPM,UPR)
```

```

REGDEF/ G6, G, 260, 260, T, 20,21    $$ UNITS SELECT (INCHES,MM)
REGDEF/ G7, G, 260, 260, F, 40,41,42  $$ CUTTER RADIUS COMPENSATION
                                     (OFF,LEFT,RIGHT)
REGDEF/ G8, G, 260, 260, F, 43,44,49  $$ TOOL LENGTH COMPENSATION
                                     (ADD,SUB,CANCEL)
REGDEF/ G9, G, 260, 260, F, 80,73,74,75,76,81,82,83,84,85,86,87,88,89  $$ CYCLE
                                     (See AZpost Users Guide)
REGDEF/ G10, G, 260, 260, F, 52,53,54,55,56,57,58,59,92  $$ FIXTURE OFFSET
                                     (LOCAL,MACH,1,2,3,4,5,6,DATUM)
REGDEF/ HH, H, 260, 260, F            $$ TOOL LENGTH COMPENSATION REGISTER
REGDEF/ XX, X, 214, 413, T            $$ LINEAR ABSCISSA AXIS
REGDEF/ YY, Y, 214, 413, T            $$ LINEAR ORDINATE AXIS
REGDEF/ ZZ, Z, 214, 413, T            $$ LINEAR NORMAL AXIS
REGDEF/ Z1, Z, 214, 413, F            $$ AXIAL DRILL DEPTH
REGDEF/ II, I, 214, 413, F            $$ ARC CENTER OFFSET PARALLEL TO ABSCISSA AXIS
REGDEF/ JJ, J, 214, 413, F            $$ ARC CENTER OFFSET PARALLEL TO ORDINATE AXIS
REGDEF/ KK, K, 214, 413, F            $$ ARC CENTER OFFSET PARALLEL TO NORMAL AXIS
REGDEF/ DD, D, 260, 260, F            $$ CUTTER RADIUS COMPENSATION REGISTER
REGDEF/ RR, R, 214, 413, F            $$ CLEARANCE PLANE AXIAL DRILL CYCLE
REGDEF/ QQ, Q, 214, 413, F            $$ INCREMENT VALUE DEEP & BREAK CHIP CYCLES
REGDEF/ AA, A, 214, 413, T            $$ ROTARY AXIS AROUND ABSCISSA
REGDEF/ FF, F, 311, 412, T            $$ FEED RATE VALUE
REGDEF/ PP, P, 244, 244, F            $$ PROGRAM DWELL VALUE
REGDEF/ SS, S, 540, 540, T            $$ SPINDLE SPEED VALUE
REGDEF/ TT, T, 240, 240, F            $$ CURRENT TOOL NUMBER
REGDEF/ T1, T, 240, 240, F            $$ NEXT TOOL NUMBER
REGDEF/ LL, L, 240, 240, F            $$ SUBROUTINE NUMBER
REGDEF/ M0, M, 260, 260, T            $$ GENERAL MISCELLANEOUS FUNCTIONS
REGDEF/ M1, M, 260, 260, F, 6         $$ TOOL CHANGE FUNCTIONS (LOAD/TOOL)
REGDEF/ M2, M, 240, 240, T, 9,8,7,12,50,51,8  $$ COOLANT FUNCTIONS
                                     (OFF,ON/FLOOD,MIST,THRU,TAP,AIR,AUX)
REGDEF/ M3, M, 260, 260, T, 5,3,4,19,21,22,41,42  $$ SPINDLE FUNCTIONS
                                     (OFF,CLW,CCLW,LOCK,CLAMP,UNCLAMP,LOW,HIGH)
REGDEF/ M4, M, 260, 260, T, 17,98,99  $$ SUBROUTINE FUNCTIONS
                                     (END,RETRCT,NO_RETRCT)
REGDEF/ M5, M, 260, 260, F, 0,1,2,30  $$ PROGRAM CONTROL FUNCTIONS
                                     (STOP,OPSTOP,END,REWIND)

```

```

EOT
$$$$*****
$$ SECTION THREE - Program MACRO Sequences
$$$$*****
$$$$***** START MACRO SEQUENCE *****
MACRO/START
" "
"% "                                $$ Rewind stop code
O(PROGID) PARTNO                    $$ Program ID
END
$$$$***** FROM MACRO SEQUENCE (3-AXIS) *****
MACRO/FROM
G3() G6() G7(40) G9(80)$            $$ Initialization Block
END
$$$$***** FROM MACRO SEQUENCE (4-AXIS) *****
MACRO/FROM4
G3() G6() G7(40) G9(80) AA(0)$     $$ Initialization Block
END
$$$$**** RETRACT MACRO SEQUENCE (Tool Change) ****

```

```

MACRO/RETRCT
M2(9)$                                $$ Coolant Off
G0(28) G3(91) YY(HOMEY) ZZ(CLEARP)$  $$ Machine Zero Y & Z-axis
END
$$***** 1ST TOOL CHANGE MACRO SEQUENCE *****
MACRO/TLCHG1
TPRINT>                                $$ Add TPRINT text to next block
TT() M1(6)$                             $$ Select & Load programmed tool
END
$$***** ALL OTHER TOOL CHANGE MACRO SEQUENCE ****
MACRO/TLCHG
" "                                     $$ Blank block before tool change
TPRINT>                                $$ Add TPRINT text to next block
TT() M1(6)$                             $$ Select & Load programmed tool
END
$$***** GOHOME MACRO SEQUENCE *****
MACRO/GOHOME
M2(9)$                                $$ Coolant Off
G0(28) G3(91) YY(HOMEY) ZZ(HOMEZ)$    $$ Machine home Y & Z axis
END
$$***** RESTART MACRO SEQUENCE (3-AXIS) *****
MACRO/RESTAR
G1(0) G3(90) G10() XX() YY() SS() M3()$  $$ 1st XY motion after Tool Change
G8() ZZ() HH() M2()$                   $$ 1st Z motion after Tool Change
END
$$***** RESTART MACRO SEQUENCE (4-AXIS) *****
MACRO/RESTAR4
G1(0) G3(90) G10() XX() YY() AA() SS() M3()$  $$ 1st XY motion after Tool Change
G8() ZZ() HH() M2()$                   $$ 1st Z motion after Tool Change
END
$$***** CYCLE ACTIVATE MACRO SEQUENCE *****
MACRO/CYCLE
G0() G9() XX() YY() Z1() RR() FF()$      $$ CYCLE (DRILL,BORE, etc)Activation
G0() G9() XX() YY() Z1() RR() QQ() FF()$  $$ CYCLE (DEEP,BRKCHIP) Activation
G9(80)$                                  $$ CYCLE De-activation Block
END
$$***** PROGRAM END SEQUENCE (3-AXIS) *****
MACRO/PRGEND
M3(5)$                                  $$ Spindle Off
G1(0) G2(28) G3(91) M2(9)$              $$ Z-axis home, Coolant Off
G1(0) G2(28) G3(91) YY(HOMEY) ZZ(HOMEZ)$  $$ Machine home XY Axis
M5(99)$                                  $$ End of Main program code
END
$$***** PROGRAM END SEQUENCE (4-AXIS) *****
MACRO/PRGEND4
M3(5)$                                  $$ Spindle Off
G1(0) G2(28) G3(91) M2(9)$              $$ Z-axis home, Coolant Off
G1(0) G2(28) G3(91) YY(HOMEY) ZZ(HOMEZ) AA(0)$  $$ Machine home XY Axis
M5(99)$                                  $$ End of Main program code
END
EOF

```